Survey form-II

D I ID	-						
Record ID	89						
FILLING STATION					Yr Built	Address ID	
Military SW, 310					1957	1874	
2nd Address					1337	1074	
+ Danalyn DrSo	merset						
Present Name							
Mundo Tile/Pro(Care Collision						
Present Use			Arch Style				
other - see note							
Plan Shape			Gas Sta For	m			
Structural Syster		Primary Wall Material					
2nd Wall Materi		Service Bays (number or no)					
				7			
Roof Type			Roof Mater	rial			
Foundation Type	2	Orig Do	ors		Orig V	Vindows	
/1	15						
Primay Windows	S		2nd Windov	VS			
Сапору Туре			Canopy Features				
Built Landscape							
Natural Landsca	20	Signag	10				
Natural Landscape Sign		Signag	lage				
Additions							
large service bui	lding attached to	back					
Alterations							
Integrity	Historic	Histor	ic Marker/Pl	aque	1983 Surv	Recent Photo	
POS				1		(1 Google)	
Notes							
			olished or gr	eatly al	tered in the 19	60s. Service bays	

Surveyor Name	Surv	ey Date
Frederica Kushner		8/29/17