

Survey form-II

| | | | | |
|--|------------|---|-----------|--------------|
| Record ID | | | | |
| 353 | | | | |
| FILLING STATION ADDRESS | | | Yr Built | Address ID |
| St. Mary's N., 3011 | | | 1922 | 354 |
| 2nd Address | | | | |
| + Kings Court | | | | |
| Present Name | | | | |
| Candlelight Coffee House | | | | |
| Present Use | | Arch Style | | |
| commercial | | may have been a dwelling, then a gas station, now a c | | |
| Plan Shape | | Gas Sta Form | | |
| rectangle | | Oblong box | | |
| Structural System | | Primary Wall Material | | |
| wood frame | | wood | | |
| 2nd Wall Material | | Service Bays (number or no) | | |
| | | no | | |
| Roof Type | | Roof Material | | |
| flat w/parapet | | not visible | | |
| Foundation Type | Orig Doors | Orig Windows | | |
| not visible | no | no | | |
| Primay Windows | | 2nd Windows | | |
| fixed/picture | | | | |
| Canopy Type | | Canopy Features | | |
| detached, hipped/half hippedl | | columns of concrete made to look like wood (faux boi | | |
| Built Landscape | | | | |
| gas pumps, island | | | | |
| Natural Landscape | | Signage | | |
| many trees | | | | |
| Additions | | | | |
| addition at back | | | | |
| Alterations | | | | |
| windows replaced - fence now surrounds building and pumps - canopy probably built in 1930s [by local faux bois artist], repaired in early 1980s [?] | | | | |
| Integrity | Historic | Historic Marker/Plaque | 1983 Surv | Recent Photo |
| high | yes | | y | (22) |
| Notes | | | | |
| 1983=built as home in 1922 - 1934, faux bois [false wood] canopy built in 1930s by local artist - restored; 2013=difficult to see from street - pumps are old but may not be original - if it's not a historic landmark, it should be - FK | | | | |

| |
|---------------|
| Surveyor Name |
| Annette Prinz |

| |
|-------------|
| Survey Date |
| 11/16/12 |