Survey form-II

| Record ID | 505 | | | | | | |
|--------------------------|--------------|-----------|-----------------------------|-----------|--------------|--------------|--|
| FILLING STATIO | | | | Yr Built | Address ID | | |
| Commerce W., | | | | 1946 | 15 | | |
| 2nd Address | | | | | | | |
| pre-1970 may h | ave been 211 | 6 W. Comn | nerce | | | | |
| Present Name | | | | | | | |
| Present Use | | | Arch Style | | | | |
| other - see note | | | | | | | |
| Plan Shape | | | Gas Sta Form | | | | |
| Structural System | | | Primary Wall Material | | | | |
| 2nd Wall Material | | | Service Bays (number or no) | | | | |
| Roof Type | | | Roof Material | | | | |
| Foundation Type | | Orig Doo | Doors | | Orig Windows | | |
| Primay Window | /S | | 2nd Windows | | | | |
| Canopy Type | | | Canopy Features | | | | |
| Built Landscape | } | | | | | | |
| Natural Landscape Sigr | | Signag | age | | | | |
| Additions | | | | | | | |
| Alterations | | | | | | | |
| | - 10 | | | | | | |
| Integrity | Historic | Histor | ic Marker/Plaqu | ie 198 | 3 Surv | Recent Photo | |
| POS | | | | | | (2) | |
| Notes Either driveway | to 1610 W. C | ommerce c | or Alazon-Apach | e Creek b | ank. | | |

Surveyor Name

Karen Glenney & Jacqueline Burandt

| Survey | Date |
|--------|------|
| | |

5/1/16