

Survey form-II

Record ID

1799

FILLING STATION ADDRESS

Santa Anna, 1639

Yr Built

1955-56

Address ID

1789

2nd Address

+ Buckeye

Present Name

[house]

Present Use

other - see note

Arch Style

Plan Shape

Gas Sta Form

Structural System

Primary Wall Material

2nd Wall Material

Service Bays (number or no)

Roof Type

Roof Material

Foundation Type

Orig Doors

Orig Windows

Primay Windows

2nd Windows

Canopy Type

Canopy Features

Built Landscape

Natural Landscape

Signage

Additions

Alterations

Integrity

Historic

Historic Marker/Plaque

1983 Surv

Recent Photo

POS

(1 Google)

Notes

House in a residential neighborhood. May be incorrect address.

Surveyor Name
Frederica Kushner

Survey Date
11/3/16