Survey form-II

Record ID 17	55						
FILLING STATION ADDRESS					Yr Built	Address ID	
Military SW, 341				1952-53	1747		
2nd Address							
+ Kelsey							
Present Name							
Moonlight Mote							
Present Use			Arch Style				
other - see note							
Plan Shape			Gas Sta Form				
Structural System			Primary Wall Material				
2nd Wall Material			Service Bays (number or no)				
Roof Type			Roof Material				
Foundation Type	2	Orig Doo	ors		Orig Wir	idows	
Primay Windows	5		2nd Windows				
Canopy Type			Canopy Features				
Built Landscape							
Natural Landsca	ne	Signag	<u>م</u>				
		0.8108	<u>, , , , , , , , , , , , , , , , , , , </u>				
Additions							
Alterations							
Integrity	Historic	Histor	ic Marker/Plaque	1983	Surv	Recent Photo	
POS						2) + (1 Google)	
Notes							
Probably demoli	shed prior to	1997, whe	n motel was built	. Canopy	is probably	v a replacement.	

Surveyor	Name
----------	------

Frederica Kushner

Survey [Date
----------	------

8/29/17