

Survey form-II

Record ID

343

FILLING STATION ADDRESS

St. Mary's N., 1201

Yr Built

1931-1937

Address ID

344

2nd Address

+ Brooklyn

Present Name

[vacant]

Present Use

other - see note

Arch Style

Spanish Eclectic

Plan Shape

vee

Gas Sta Form

Oblong box with canopy

Structural System

concrete

Primary Wall Material

concrete

2nd Wall Material

Service Bays (number or no)

2

Roof Type

flat w/parapet

Roof Material

not visible

Foundation Type

slab

Orig Doors

no

Orig Windows

no

Primay Windows

fixed/picture

2nd Windows

Canopy Type

attached, flat

Canopy Features

brick columns/posts, brick columns/posts - tile at roof

Built Landscape

island

Natural Landscape

Signage

Additions

Alterations

Integrity

high

Historic

yes/landmark

Historic Marker/Plaque

1983 Surv

y

Recent Photo

(6)

Notes

2012=vacated; 2017=owned by Cath. School - canopy has tin ceiling.

By 2020 canopy enclosed, addition between canopy & service bays, other alterations.

Surveyor Name
Annette Prinz

Survey Date
11/12/12