

Survey form-II

| |
|-----------|
| Record ID |
| 36 |

| | | |
|-------------------------|-----------|------------|
| FILLING STATION ADDRESS | Yr Built | Address ID |
| Buena Vista, 1202 | 1931-1932 | 31 |

| |
|---------------|
| 2nd Address |
| + S. Colorado |

| |
|---------------------|
| Present Name |
| Buena Vista Gardens |

| | |
|-------------|------------|
| Present Use | Arch Style |
| unknown | Mission |

| | |
|------------|--------------|
| Plan Shape | Gas Sta Form |
| rectangle | Oblong box |

| | |
|-------------------|-----------------------|
| Structural System | Primary Wall Material |
| not visible | stucco |

| | |
|-------------------|-----------------------------|
| 2nd Wall Material | Service Bays (number or no) |
| | |

| | |
|----------------|---------------|
| Roof Type | Roof Material |
| flat w/parapet | not visible |

| | | |
|-----------------|------------|--------------|
| Foundation Type | Orig Doors | Orig Windows |
| slab | no? | no? |

| | |
|----------------|-------------|
| Primay Windows | 2nd Windows |
| unknown | |

| | |
|-------------|-----------------|
| Canopy Type | Canopy Features |
| none | |

| |
|-----------------|
| Built Landscape |
| |

| | |
|-------------------|------------------------|
| Natural Landscape | Signage |
| | possible historic sign |

| |
|--|
| Additions |
| lights attached to façade; mural on side of building |
| |

| |
|------------------------------|
| Alterations |
| windows and doors boarded up |
| |

| | | | | |
|-----------|----------|------------------------|-----------|--------------|
| Integrity | Historic | Historic Marker/Plaque | 1983 Surv | Recent Photo |
| high | y | Landmark | y | (1)+4 |

| |
|---|
| Notes |
| 2013 - under restoration; brickwork & tile ornamentation on façade - NALAC is present owner |
| |

| |
|----------------|
| Surveyor Name |
| Rachel Delgado |

| |
|-------------|
| Survey Date |
| 4/20/13 |