## Survey form-II

Record ID	03						
FILLING STATION			Yr Built	Address ID			
Castroville, 1013			1951	1700			
2nd Address					1331	1700	
955 S. Gen. McN	1ullen						
Present Name							
O'Reilly Auto Par	ts parking lot						
Present Use			Arch Style				
parking lot							
Plan Shape			Gas Sta Form				
Structural System			Primary Wall Material				
2nd Wall Material			Service Bays (number or no)				
Roof Type			Roof Material				
Foundation Type	)	Orig Doo	ors		Orig W	'indows	
Duine ou Min doug			2nd Windows				
Primay Windows			zna windows				
Сапору Туре			Canopy Features				
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							
Built Landscape							
Natural Landscape Signa		Signag	де				
Additions							
Alterations							
riterations							
Integrity	Historic	Histor	ic Marker/Plac	que 19	983 Surv	Recent Photo	
Notes							
No evidence of gas station.							

	6 9 .
Surveyor Name	Survey Date
Frederica Kushner	10/12/16