

Survey form-II

Record ID

1894

FILLING STATION ADDRESS

Castroville, 0242

Yr Built

1960

Address ID

1877

2nd Address

between Barclay & SW 21st St. - 246 Castroville

Present Name

no name

Present Use

automotive

Arch Style

Craftsman

Plan Shape

rectangle

Gas Sta Form

House

Structural System

not visible

Primary Wall Material

2nd Wall Material

Service Bays (number or no)

2(?)

Roof Type

side gable

Roof Material

metal-standing seam

Foundation Type

not visible

Orig Doors

yes

Orig Windows

no

Primay Windows

2nd Windows

Canopy Type

none

Canopy Features

Built Landscape

parking area

Natural Landscape

Signage

none

Additions

smaller side gabled addition to one side, even smaller flat-roofed addition w/shed-like awning across front

Alterations

hard to determine

Integrity

low

Historic

Historic Marker/Plaque

1983 Surv

Recent Photo

(4 Google)

Notes

This may or may not have been a gas station, but looks like an automotive repair shop. 242 may have been the number of the small building w/front awning.

| Surveyor Name |
|-------------------|
| Frederica Kushner |

| Survey Date |
|-------------|
| 12/8/19 |