

# Survey form-II

Record ID				
8				
FILLING STATION ADDRESS			Yr Built	Address ID
Alamo N., 1835			1931-32	3
2nd Address				
+ Grayson				
Present Name				
1800 Broadway Lofts apartments				
Present Use		Arch Style		
other - see note				
Plan Shape		Gas Sta Form		
Structural System		Primary Wall Material		
2nd Wall Material		Service Bays (number or no)		
Roof Type		Roof Material		
Foundation Type	Orig Doors	Orig Windows		
Primay Windows		2nd Windows		
Canopy Type		Canopy Features		
Built Landscape				
Natural Landscape		Signage		
Additions				
Alterations				
Integrity	Historic	Historic Marker/Plaque	1983 Surv	Recent Photo
POS			y	(2) + 8 Google-200
Notes				
1983: Added building on Grayson St. but orig. garage appears to be storage; small brick building w tin ceiling on canopy, flat roof with tile edge; present garage is add-on facing Grayson St. (see Google photos)- 2013: Demolished btwn 2008-2011				

Surveyor Name
Pat Ezell & Caitlin Brown

Survey Date
10/7/13