

Survey form-II

Record ID
211

FILLING STATION ADDRESS	Yr Built	Address ID
Laredo S., 1019	1927	212

2nd Address

Present Name
Humble sign on side of building

Present Use	Arch Style
unknown	Art Deco

Plan Shape	Gas Sta Form
oval	Lozenge with canopy, Other

Structural System	Primary Wall Material
brick	brick

2nd Wall Material	Service Bays (number or no)
stucco	no

Roof Type	Roof Material
hipped	

Foundation Type	Orig Doors	Orig Windows
not visible	yes	yes

Primay Windows	2nd Windows

Canopy Type	Canopy Features
attached, flat	brick columns/posts, brick columns/posts; tilework

Built Landscape
island

Natural Landscape	Signage

Additions

Alterations
dog kennel fence at back of building

Integrity	Historic	Historic Marker/Plaque	1983 Surv	Recent Photo
high	yes		y	(6)

Notes
1983 - "showcase station"; 2013=not in use, is adjacent to the kennel, tilework still intact - most doors bricked in, multi-lite picture windows in front have been covered over.

Surveyor Name
Rachel Delgado

Survey Date
4/20/13