

Survey form-II

Record ID

1966

FILLING STATION ADDRESS

Lexington, 0818

Yr Built

1931

Address ID

1942

2nd Address

+ E. Maple - was 1102 Lexington

Present Name

San Antonio Diagnostic Imaging

Present Use

parking lot

Arch Style

Plan Shape

Gas Sta Form

Structural System

Primary Wall Material

2nd Wall Material

Service Bays (number or no)

Roof Type

Roof Material

Foundation Type

Orig Doors

Orig Windows

Primay Windows

2nd Windows

Canopy Type

Canopy Features

Built Landscape

Natural Landscape

Signage

Additions

Alterations

Integrity

Historic

Historic Marker/Plaque

1983 Surv

Recent Photo

POS

(2 Google)

Notes

Gas station demolished sometime after 1960.

Surveyor Name
Frederica Kushner

Survey Date
10/12/20