

Survey form-II

Record ID

1746

FILLING STATION ADDRESS

El Paso, 0602

Yr Built

1948

Address ID

1740

2nd Address

Present Name

GLI Distributing

Present Use

other - see note

Arch Style

Plan Shape

Gas Sta Form

Structural System

Primary Wall Material

2nd Wall Material

Service Bays (number or no)

Roof Type

Roof Material

Foundation Type

Orig Doors

Orig Windows

Primay Windows

2nd Windows

Canopy Type

Canopy Features

Built Landscape

Natural Landscape

Signage

Additions

Alterations

Integrity

POS

Historic

Historic Marker/Plaque

1983 Surv

Recent Photo

(1 Google)

Notes

600 blk. of El Paso no longer exists. GLI Distributing parking lot & entrance.

Surveyor Name
Frederica Kushner

Survey Date
10/13/16