

Survey form-II

Record ID

209

FILLING STATION ADDRESS

Laredo S., 0801

Yr Built

1927-1928

Address ID

210

2nd Address

+ El Paso

Present Name

Present Use

vacant lot

Arch Style

Plan Shape

Gas Sta Form

Structural System

Primary Wall Material

2nd Wall Material

Service Bays (number or no)

Roof Type

Roof Material

Foundation Type

Orig Doors

Orig Windows

Primay Windows

2nd Windows

Canopy Type

Canopy Features

Built Landscape

Natural Landscape

Signage

Additions

Alterations

Integrity

Historic

Historic Marker/Plaque

1983 Surv

Recent Photo

POS

y

(1)

Notes

1983 - "also Grayburg #21; Texport #20" [1st to include photographic prints]; 2013=gone - photographed in 1983, but demolished between 1983 and 2013 surveys

Surveyor Name
Rachel Delgado

Survey Date
4/20/13