LOWELL CULTURAL RESOURCES INVENTORY _____ MAP SHEET # __140 IDENTIFICATION 8 Wamesit Court 1) CURRENT OWNER Arthur F. and Shirley Maniatis OWNER OCCUPIED yes 2) HISTORIC NAME _____ 3) CURRENT NAME 4) PROPERTY TYPE ______ single family dwelling _____ 5) ZONING CLASSIFICATION ____ IA 6) TAXES: PAYMENTS _____ current _____ STATUS ___clear 7) WITHIN BOUNDARIES OF _____LHPD HISTORICAL ABSTRACT 1) CONSTRUCTION DATE _____ca.18 30 (moved to present site ca.1860) SOURCE style, city directories, 1980 Shepley Bulfinch report 2) ARCHITECT OR BUILDER _____ 3) HISTORIC OWNER _____ 4) ORIGINAL USE: GF residential UF 5) PREVIOUS BLDGS ON PROPERTY ______ DATE _____ SOURCE ____ VIEW FROM ______ northeast PHOTO TAKEN _____ Nov.1992 DESCRIPTIVE DATA 1) ARCHITECTURAL STYLE vernacular 2) PRESENT USE: GF residential UF _____ 3) NO OF STORIES $\frac{1}{2}$ 1/2 rectangular 5) PLAN with side ell 6) ROOF endwall gable 7) STRUCTURAL SYSTEM wood frame 8) OUTBUILDINGS 9) MATERIALS: FOUNDATION rubblestone aesbestos siding over wood clapboards

FACADE___

<u>VISUAL ASSESSMENT</u>
1) CONDITION OF BUILDING FABRIC <u>needs minor repair</u>
2) IF DETERIORATED, CAUSES <u>lack of maintenance</u>
3) INTEGRITY OF HISTORIC BLDG FABRIC: GF <u>intact with minor changes</u>
UFn/a
4) SURROUNDING LAND USES <u>residential, light industrial, storage</u>
5) INTEGRITY OF PROPERTY'S HISTORIC SETTING (moved to present site ca.1860)

ADDITIONAL DESCRIPTION

ADDRESS Eight Wamesit Court

One Wamesit Court is part of a group of small frame vernacular houses which date ca.1830 but were moved to their present site about 1860. Until late 1992, when #7 was demolished, there were six of these 1 1/2 story houses, arranged in two groups of three attached units facing each other across a central alley. The houses consist of a main block and side wings which attach to the adjacent house(s). Eight Wamesit Court is a single family house which connects to #4, which in turn connects to #2. The simple structure is 6 bays across. The main entrance at the fourth bay has transom lights above. Window sash is 6/6. The house has a rear enclosed porch. The chimney is located in the center on the ridge. Siding is asphalt over the original clapboards.

ADDITIONAL HISTORICAL INFORMATION
SOURCES
SKETCH MAP

See Research Report (#1 Wanes it Court)

6) IMPORTANCE OF PROPERTY TO HISTORIC SETTING __integral to character

ARCHEOLOGICAL COMMENT

Archeological remains which could be recovered in the very small yard would relate to domestic use of the site since 1860.