LOWELL CULTURAL RESOURCES INVENTORY

ID	ENTIFICATION	Foot of HOWE STR	REET	MAP SHEET #12
	CURRENT OWNER			
2)	HISTORIC NAME	Site of Belvider	ce Woolen Manufacturin	g Co. Mill No. 1
3)	CURRENT NAME	same	The second secon	
4)	PROPERTY TYPE	archeological	5) ZONING CLASS	IFICATION B-1
6)	TAXES: PAYMENTS	exempt	STATUS clear	
7)	WITHIN BOUNDARIES OF	LHPD (partial)		
HI	STORICAL ABSTRACT			
1)	CONSTRUCTION DATE	n/a		
	SOURCE	n/a		
2)	ARCHITECT OR BUILDER			
3)	HISTORIC OWNER	Belvidere Woolen	Manufacturing Compan	У
4)	ORIGINAL USE: GF	n/a	UF n/a	
5)	PREVIOUS BLDGS ON PROPE	RTY yes DATE	ca. 1818-ca. 1930s	
	SOURCE	circumstantial:	see Research Report	
DE	SCRIPTIVE DATA	The state of the s	1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	
1)	ARCHITECTURAL STYLE	VIEW FROM _	southeast PHOTO TA	KEN <u>November</u> 1979
	n/a			
2)	PRESENT USE:	f.		7
	GF parking lot	The same of	V L	
,	UFn/a		_	PHILIPPI PROPERTY PROPERTY
	NO OF STORIES n/a			
4)	PROP SQ FT 93, (Partial)			
5)	PLANn/a			
6)	ROOFn/a			
7)	STRUCTURAL SYSTEM			
	n/a			
8)	OUTBUILDINGS			
	none			
9)	MATERIALS:			
	FOUNDATION			
	n/a			encountries are expressed in the second of t
	FACADE n/a	and the second s	and the same of the state of the same of t	
	TRIMn/a			
10)	NOTABLE SURFACE & LANDS		ndation retaining wal	1 payed areas

mature trees, waterpower components

VISUAL ASSESSMENT

1)	CONDITION OF BUILDING FABRIC	n/a	_
2)	IF DETERIORATED, CAUSES	n/a	
3)	INTEGRITY OF HISTORIC BLDG FABRIC: GF_	n/a	
	UF_	n/a	
4)	SURROUNDING LAND USES commerci	al, industrial, residential, river frontag	ge
5)	INTEGRITY OF PROP'S HIST SETTING	severely disrupted historic setting	
6)	IMPORTANCE OF PROP TO HIST SETTING	character so disrupted question n/a	

ADDITIONAL DESCRIPTION

See Research Report.

The City of Lowell owns a sizable parcel of land (over 90,000 sq. ft.) on the east bank of the Concord River just south of East Merrimack Street. The LHPD boundary bisects this parcel, including somewhat less than half of it in the District.

The most notable features of this property are located in its southern half, along the riverbank. The concrete Middlesex Company dam crosses the Concord River in this area, ponding the river to the south.



View from the southeast of the Belvidere site, from the Church Street Bridge.

Photo taken in November, 1979.

The dam extends from the west bank to a small, tree-covered island near the

east bank. The island is separated from that shore by a narrow spillway beween concrete abutments, spanned by I-beams.



View from the southeast of the spillway separating the Belvidere site (right) from the island at the east end of the Middlesex Company dam.

Photo taken in November, 1979.



View from the northwest of the spillway. The Belvidere site is to the left, island to the right.

Photo taken in November, 1979.

ADDRESS:

That island and the riverbank north and south of it contain numerous walls, footings, and abutments of granite, concrete, and rubble stone related to the mills which operated on this site and to their waterpower systems.



Two rubble stone abutments on the Concord riverbank at the Belvidere site.

View from the northwest.

Photo taken in November, 1979.

ADDITIONAL HISTORICAL INFORMATION

See Research Report, pp. 1-5, 7, 8, and Figures.

Thomas Hurd owned a sawmill on this site as early as 1818, and woolen mills operated on the property by 1821. Hurd built the first dam at this point in the Concord to power mills on both banks. After he sold off the main part of his east bank holdings in 1821, he retained ownership of the west bank millyard, and

the island at the east end of his dam. The individuals and corporations that succeeded Hurd in the western millyard, most notably the Middlesex Manufacturing Company, retained title to the east island into the twentieth century but sometimes leased it to Belvidere Woolen and other operators of the east bank millyard.

ARCHEOLOGICAL COMMENT

See Research Report, pp. 8 and 9.